

Job Description

Job Title:	Rubber Pressman operator
Reports To:	Supervisor
Job Type:	Temp to Hire – Full Time
Shift:	Monday 3:45 pm – 7:45 pm (4 hour shift) Tue-Thu 7:45 am to 7:45 pm (12 hours per shift)
Hourly Rate:	Training rate starts at \$18.00 per hour and increased with performance improvement
Location:	Fall River, MA
Language	English
Attire	Closed Toe Shoes / Non-Slip

Position Description:

As a Rubber Pressman Operator in an industrial plant with a focus on plastic injection molding, you manage seven machines, ensuring they run efficiently. Your responsibilities include operating machinery, handling materials, resetting alarms, and performing manual tasks like reaming and trimming with precision. Attention to detail is crucial as you conduct color testing and inspect production to guarantee 100% quality. Safety is a priority, and you engage in tasks ranging from driving a forklift to changing propane fuel tanks. Additionally, you maintain a clean work area, adhere to proper safety measures, and communicate effectively with team members regarding any issues. Your role involves various duties, reflecting adaptability and a commitment to departmental and plant operations.

Specific Duties & Responsibilities:

1. In an industrial plant, operate and run all plastic injection molding machines (currently 7 machines). Requires standing, bending, lifting. Floors are concrete and need the ability to walk on slippery surfaces.
2. Run correct material and color concentrate on each job.
3. Reset injection molding machine or auxiliary equipment alarms.
4. Perform reaming and trimming functions by hand (using a razor knife) at a rate that keeps pace with machine. Requires excellent eye/hand coordination and hand/wrist dexterity.
5. Put different inserts into wheels using a manual inserter.
6. Use proper safety precautions while operating or working on machinery.
7. Inspect production and be sure the customer receives 100% good product. Inspection includes color testing by eye.
8. Label all production with employee number.
9. Run Inspection Conveyor.
10. Sort and pack products into boxes.
11. Take runners (plastic waste) and regrind for reuse.
12. Drive a forklift truck.
13. Change a forklift truck propane fuel tank.

ROBERTS

JOSEPH

STAFFING

14. Make boxes and covers (using air staple gun).
15. Notify (1) an operator and (2) Frank or Ted of problems with a machine, product or quality in a timely manner.
16. Complete necessary operation and production records as required.
17. Keep work area clean.
18. Perform any other duties that may be assigned.
19. Perform all duties consistent with department and plant operations.
20. Must be able to pass a written Molder's test, after training period.

Roberts Joseph Staffing: New Bedford MA 0274
Phone Number: 774-510-5651
Email: recruiting@robertsjoseph.com